

# SCULPFUN RA Mini



SCULPFUN RA Mini



Support Wheel Stand



Motor Cable



C1 Machine Riser



Nut



Wrench



Zip Tie



Measuring Tape



User's Manual



Scan the QR code to access the video tutorial

Customer Support: [support@sculpfun.com](mailto:support@sculpfun.com)

Official Website: [sculpfun.com](http://sculpfun.com)



## SCULPFUN iCube Ultra


Max Supported Diameter: 85mm

Port: Dedicated Port (on the right side of the smoke exhaust grille)

After connecting the roller, enter the command in lightburn

\$45=1 (roller on)

\$45=0 (roller off)



## SCULPFUN C1

Max Supported Diameter: 100mm

Port: Connection cable of Y-axis stepper motor



## SCULPFUN iCube

Max Supported Diameter: The maximum engraving size depends on the height of the riser used.

(Users need to prepare the risers!)

Port: Y-axis port is on the motherboard

(Remove the top cover of the machine, connect the RA mini motor cable to Y-axis port, and set the Y-axis to reverse in LightBurn; otherwise, the engraving will be mirrored.)

**Scan the QR code to view detailed operations**